

CESSNA RESTART AIRCRAFT SERVICE BULLETIN SUMMARY

As of 7-5-04

Mandatory compliance unless stated otherwise

Notice - All bulletins: parts and labor credit expires on date published in bulletin or end of two year aircraft warranty, which ever is later.

04 Service Bulletins

SB04-11-01	Pilot's operating handbook and checklist rev.	T/206H	3-01-04	
SB04-24-01	Alternator control unit inspection/replacement	172/182/206series	3-01-04	
SB04-25-01R1	Crew seat recline modification	172/182/206series	6-14-04	
SB04-25-02	Crew seat back cyl. lock insp. & crank arm mod.	172/182/206series	6-14-04	
SB04-27-01R1	Elevator rivet inspection	T/182T	4-26-04	
SB04-27-02	Elevator trim tab control cable inspection	172R-S	4-12-04	
SB04-28-01R1	Fuel hose inspection	172R-S	4-05-04	
SB04-28-02	Fuel strainer installation inspection	T/182T	5-10-04	
SB04-32-01	NLG shock strut metering pin replacement	172R-S	2-02-04	
SB04-52-01	Security lock installation	172/182/206series	6-28-04	Optional
SB04-53-01	Bulkhead rivet inspection	T/206H	3-01-04	
SB04-55-01	Horizontal stabilizer attach bolt holes inspection	172R-S	4-12-04	
SB04-71-01	Engine cowl flap rivet inspection	T/182T	4-26-04	Recommended

04 SB total 13

03 Service Bulletins

SB03-11-01	Pilot's operating handbook and checklist rev.	206H	2-17-03	
SB03-11-02	Pilot's operating handbook and checklist rev.	172R	4-14-03	
SB03-11-03	Brazilian pilot's operating handbook revision	206H	6-23-03	
SB03-11-04	Pilot's operating handbook and checklist rev.	172R-S	10-27-03	
SB03-23-01	Honeywell KMA26 audio panel modification	172/182/206series	7-28-03	Recommended
SB03-24-01	Alternator replacement	172/182/206series	7-28-03	Recommended
SB03-24-02	MC01-3A main electrical power "J" box mod.	172/182/206series	10-13-03	Recommended
SB03-25-01	Armrest shield installation	172R-S	2-03-03	Optional
SB03-27-01	Flap actuator motor inspection	T/182T	9-29-03	
SB03-27-02	Flap control bracket attach bolts replacement	172/182/206series	12-22-03	
SB03-28-01	Fuel cap lanyard removal	172/182/206series	10-27-03	Optional
SB03-32-01	Nose landing gear wheel fairing modification	172/182/206series	9-29-03	Optional
SB03-34-01	Honeywell KS 270,271,272 C servo friction insp.	172/182/206series	10-27-03	Recommended
SB03-34-02R1	Altimeter inspection	172/182/206series	2-16-04	
SB03-37-01	Vacuum manifold inspection/replacement	172/182/206series	11-10-03	
SB03-53-01	Aft cabin stringer inspection	T/182T	5-26-03	
SB03-53-02R1	Lower cabin doorpost to MLG spring insp.	T/206H	6-23-03	
SB03-53-03R1	NLG fairing attachment inspection	T/182T	3-15-04	
SB03-71-01	Engine fuel supply system modification	172R-S	5-26-03	Optional
SB03-71-02	Fuel injection servo inspection	172/182series	5-26-03	
SB03-73-01	Throttle arm retention inspection	172/182/206series	11-4-03	

03 SB total 21

02 Service Bulletins

SB02-11-01	Pilot's operating handbook revisions	T182T	1-21-02	
SB02-11-02	Pilot's operating handbook revisions	182S	1-21-02	
SB02-11-03	Pilot's operating handbook revisions	T/206H	5-13-02	
SB02-11-04	Pilot's operating handbook revisions	T/206H	9-30-02	

SB02-22-01	Honeywell KAP 140 autopilot system mod.	172/182/206series	11-25-02	AD2003-24-13
SB02-25-01	Pilot and copilot shoulder harness guide removal	172/182/206series	4-29-02	Optional
SB02-28-01R1	Fuel line inspection	T/182T	12-16-02	
SB02-34-01	Goodrich WX-500 weather mapping sensor mod.	182/206series	11-25-02	Optional
SB02-37-01	Vacuum system reducer fitting replacement	T/182T	1-21-02	
SB02-37-02	Dry vacuum pump and coupling replacement	172/182/206series	2-18-02	
SB02-37-03	Vacuum system reducer fitting replacement	172/182/206series	2-18-02	Recommended
SB02-37-04	Airborne air & fuel products check valve manifold	172/182/206series	10-28-02	
SB02-52-01	Cabin door handle replacement	172/182/206series	1-21-02	
SB02-53-01	Fuselage ballast weight installation	T/182T	9-02-02	Optional
SB02-53-02	Firewall sealant installation	172R-S	12-16-02	
SB02-55-01	Elevator rivet installation	182 series	10-14-02	Recommended
SB02-61-01	Propeller spinner and bulkhead inspection	172R-S	1-21-02	Recommended
SB02-61-02	Propeller blade inspection	172R-S	12-16-02	
SB02-71-01	Engine cylinder drain can installation	T/206H	8-05-02	Optional
SB02-71-02	Engine crankshaft core sample inspection	T206H	9-23-02	
SB02-71-03R2	Engine crankshaft gear retaining bolt replacement	182S, T/206H	5-10-04	AD2002-23-06
SB02-71-04	Engine induction system fuel overboard drain	T182T	11-25-02	Optional
SB02-71-05R1	Engine oil pump plug inspection	T182T, T/206H	2-03-03	

02 SB total 23

01 Service Bulletins

SB01-11-01	Pilots operating handbook revisions	172/206series	2-05-01	
SB01-11-02	Pilots operating handbook revisions	172R-S	3-05-01	AD2001-06-17
SB01-11-03	Airplane wt. & bal. And installed equip.	T206H	6-25-01	
SB01-11-04	Pilots operating handbook revisions	T/206H	7-23-01	
SB01-25-01	Glareshield shroud installation	182/206series	12-24-01	
SB01-27-01R1	Elev. trim tab control cable stop block insp.	172S	2-19-01	
SB01-27-02	Control yoke assembly inspection	172R-S	5-28-01	
SB01-28-01	Fuel selector shaft assy. insp/mod.	T/206H	1-22-01	
SB01-28-02	Fuel selector shaft assy. insp/replacement	172R-S	5-28-01	
SB01-28-03	Fuel shut-off valve contro cable inspection	172R-S	7-23-01	
SB01-28-04	Fuel quantity level sender/transmitter insp.	T/182T-S	10-01-01	
SB01-28-05	Fuel line inspection	T/206H	12-24-01	
SB01-34-01	Com antenna replacement	T/182T	9-03-01	
SB01-53-01	Battery box support insp/mod	172R-S	2-05-01	Optional
SB01-53-02	Battery box tray liner installation	T/206H	9-03-01	
SB01-55-01	Elev. Balance wt. attach screw insp/install	172R-S	4-02-01	Recommended
SB01-71-01	Engine fuel flow divider installation mod.	172R-S	1-22-01	Optional
SB01-71-02	Engine crankshaft inspection	172R-S	4-02-01	
SB01-71-03	Engine turbocharger mounting bracket bolt	T182T	8-20-01	
SB01-71-04	Engine oil filler tube replacement/modification	T/206H	10-29-01	
SB01-73-01	Engine driven fuel pump inspection	172R-S/182S/206H	5-28-01	
SB01-73-02	Engine driven fuel pump relief valve housing repl.	T206H	9-17-01	
SB01-74-01	Ignition switch center ground terminal insp.	172/182/206series	6-25-01	Recommended

01 SB total 23

00 Service Bulletins

SB00-11-01	German pilots operating handbook revision	172R	3-13-00	
SB00-11-02	POH rev.1	T206H	4-24-00	
SB00-11-03	POH rev.4	172R	5-22-00	
SB00-11-04	POH rev 1	172S	8-14-00	
SB00-11-05	POH rev 3	182S	12-26-00	

SB00-22-01	KAP-140 autopilot servo insp/mod	172/182/206series	2-14-00	AD2000-05-24
SB00-24-01	Main power j-box C/B retrofit kit install	172/182/206series	3-13-00	Recommended
SB00-24-02	Electical panel wiring mod.	172/182/206series	6-05-00	
SB00-25-01	Engine winterization Kit installation	206H	1-31-00	
SB00-27-01R1	Lwr. fwd.elevator control cable pulley brack.	182S	8-28-00	
SB00-27-02R1	Aileron control cable quadrant insp/mod.	182S/206series	11-06-00	
SB00-32-01	NLG strut brace & drag link clearance insp.	T/206H	11-20-00	Recommended
SB00-34-01	Pitot tube heater assy. insulation installation	172/182/206series	4-10-00	
SB00-37-01	Vacuum system air filter element insp/replace	172/182/206series	8-14-00	Recommended
SB00-53-01R1	Center Cabin Rivet insp/installation	182S	8-14-00	
SB00-53-02	Rivet inspection/installation	T/206H	6-12-00	
SB00-55-01	Rudder Attach bolt torque inspection	172R-S	4-10-00	Recommended
SB00-55-02	Elevator trim tab modification	T/206H	7-31-00	
SB00-55-03	Horizontal stabilizer reinforcement insp/mod	T/206	8-28-00	AD2001-09-06
SB00-57-01R1	Flap track and wing inbrd trailing edge insp.	172R-S	4-28-03	Recommended
SB00-61-01	Propeller governor control cable routing mod.	T/206H	7-03-00	Recommended
SB00-61-02	Propeller hub inspection	172R-S	8-14-00	
SB00-73-01R2	Engine fuel injection lines and support clamps	172/182/206series	12-24-01	AD2002-26-01
SB00-79-01R1	Engine low oil pressure switch replacement	172/182/206series	2-21-00	AD2000-04-01

00 SB total 24

99 Service Bulletins

SB99-11-01	POH rev. 3	172R	9-27-99	
SB99-11-02	German POH rev. 1	182S	9-27-99	
SB99-21-01	Fresh air vent replacement	172/182/206series	3-15-99	Optional
SB99-24-01	Electrical power system mod.	172R-S/182S	3-15-99	
SB99-24-02	Circuit panel assy cover installation	172/182/206series	12-27-99	Recommended
SB99-25-01R1	ELT operational test	172/182/206series	12-27-99	
SB99-27-01	Control yoke pivot bolt insp/replacement	172R	7-12-99	AD99-18-14
SB99-28-01	Wing fuel tank vent check valve inspection	172/182/206series	4-26-99	
SB99-32-01	Brake torque plate inspection	182S	5-10-99	
SB99-34-01R1	KLN 89B GPS Nav sys. Mod.	172/182/206series	4-24-00	
SB99-37-01	Vacuum hose modification	172/182/206series	12-27-99	Recommended
SB99-53-01	Firewall doubler inspection	182S	3-08-99	
SB99-53-02	Tailcone skin installation inspection	182S	4-26-99	
SB99-53-03R1	Elev. Control yoke engagement insp/mod.	172R-S	7-28-03	
SB99-55-01	Vertical fin aft spar inspection	172R-S	3-29-99	
SB99-71-01R2	Engine piston pin plug inspection	172R-S/182S	7-12-99	Recommended
SB99-71-02	Engine oil filler tube to eng mount clearance	172R-S	7-12-99	Optional
SB99-71-03	Engine exhaust to baffle clearance	206H	8-16-99	
SB99-71-04	Alternate air door hinge assy insp/rep.	T/206H	9-13-99	
SB99-71-05	Engine valve seat inspection	172/182/206series	10-25-99	
SB99-71-06	Tailpipe Lanyard install and F/F transducer	T206H	12-06-99	
SB99-73-01R1	Engine fuel manifold spring replacement	172/206series	9-30-02	Recommended
SB99-73-02	Engine fuel injector unit inspection	172R	2-01-99	Recommended
SB99-73-03	Engine fuel pump relief valve cover screws	T206H	9-13-99	

99 SB total 24

98 Service Bulletins

SB98-11-01	Voltage polarity placard	172R	3-23-98	
SB98-11-02	POH Rev. 2	172R	3-30-98	
SB98-11-03	POH Rev. 2	182S	5-04-98	
SB98-11-04	Muffler inspection placard	182S	8-24-98	

SB98-11-05	German POH rev. 1 & 2	172R	9-21-98
SB98-11-06	Brazil POH rev. 1	172R	10-12-98
SB98-11-07	Brazil POH rev. 1	182S	10-12-98
SB98-20-01R1	Firewall sealant replacement	172R/182S	12-31-98
SB98-22-01	KAP-140 dual axis auto pilot mod	182S	5-18-98
SB98-22-02R2	KAP-140 dual axis auto pilot limitation	182S	2-01-99
SB98-24-01	Alternator replacement	172R/182S	3-30-98
SB98-25-01	Crew seatback pivot fitting insp.	172R/182S	6-01-98
SB98-25-02	Seat roller inspection	172R/182S	9-14-98
SB98-27-01	Flap follow up system	172R	3-30-98
SB98-27-02R1	Aileron cable routing	172R	12-31-98 AD98-13-41
SB98-27-03	Aileron cable clamp insp.	172R	6-01-98 AD98-13-41
SB98-27-04	Control column screw insp.	182S	6-01-98
SB98-27-05R2	Right wing aileron cable insp.	172R	12-31-98 AD98-13-41
SB98-27-06	Flight control cables and travel	172R/182S	6-15-98 AD98-13-41
SB98-27-07	Control yoke bushing	172R	9-21-98
SB98-28-01	Engine fuel transducer	172R/182S	3-02-98
SB98-28-02R1	Fuel hose clamp inspection	172R	2-01-99
SB98-28-03	Fuel shut off clamp	172R	5-04-98
SB98-34-01R1	KLN 89B GPS limitation	172R/182S	8-03-98
SB98-37-01R1	Airborne vacuum pump insp.	172R-S/182S	3-08-99 AD98-23-01
SB98-52-01	Baggage door seal replacement	172R	2-23-98
SB98-53-01R1	Firewall rivet inspection	172R	12-14-98
SB98-53-02R2	Firewall inspection	172R	12-26-00
SB98-55-01	Elevator stop bolt nutplate replace.	172R	7-06-98
SB98-55-02	Horiz. stab inbrd skin rivet inspect.	172R	7-27-98
SB98-55-03	Horiz. Stab fwd inbrd rib inspection	182S	11-30-98
SB98-57-01	Wing strut attach bolt torque insp.	172R	6-01-98
SB98-71-01	Heat shroud fwd. Baffle	172R	7-27-98 Optional
SB98-71-02	Engine air filter replacement	172R/182S	7-27-98 Recommended
SB98-78-01	Engine exhaust muffler insp.	172R	1-10-98 AD98-02-05
SB98-78-02R1	Engine exhaust muffler insp.	182S	12-14-98 AD98-13-10
SB98-78-03	Engine exhaust muffler replacement	182S	12-14-98 AD00-02-14

98 SB total 37

97 Service Bulletins

SB97-11-01	POH Rev. 1	172R	5-12-97
SB97-11-02	POH Rev. 1	182S	7-01-97
SB97-11-03R1	Autopilot limitation placard	182S	9-21-98
SB97-11-04	Aft baggage placard	172R	11-03-97
SB97-11-05	Altimeter certification log.	172R/182S	12-15-97
SB97-22-01	KC 140 Sw imp. Errors	172R/182S	10-06-97
SB97-24-01	Wire bundle inspection	172R	12-15-97
SB97-24-02	Wire bundle inspection	182S	12-22-97
SB97-25-01	Aft bench seat weld	172R	8-11-97
SB97-26-01	Fire ext. mount bracket	172R/182S	12-22-97
SB97-27-01R1	Elevator and trim pulley	172R	12-14-98
SB97-28-01	Fuel strainer and tail pipe	172R	6-06-97 AD97-12-06
SB97-28-02	Fuel tank vent line	182S	11-17-97
SB97-33-01R1	Light dim module resistor	172R/182S	12-14-98
SB97-34-01	KLN 89 GPS app. Restrictions	172R/182S	7-02-97
SB97-34-02R1	Alt. static source valve	172R/182S	12-22-97 AD98-01-01
SB97-53-01	Fuselage bulkhead	172R	7-01-97
SB97-53-02R1	Lower. fwd. doorpost fastener	172R	11-30-98 AD98-14-07
SB97-71-01R1	Alt. air door hinge assy	172R/182S	7-27-98

SB97-71-02	Engine induction drain line	172R	12-22-97
SB97-78-01	Engine exhaust nut torque	172R/182S	8-11-97
SB97-78-02	Engine exhaust muffler replacement	182S	2-02-98 AD98-01-14

97 SB total 22

04 Special Service Project

SSP04-11-01	Airplane identification data plate insp/repl.	T182T	2-02-04
SSP04-11-02	Pilot's operating handbook revision & sup 3 rev.	182T	7-05-04
SSP04-71-01	Engine cylinder drain line insp/mod.	206H	4-26-04

04 SSP total 3

03 Special Service Project

SSP03-11-01	Fuel capacity placards replacement	T206H	7-28-03
SSP03-27-01	Elevator control cable turnbuckles inspection	182S-T	11-10-03
SSP03-28-01	Fuel selector valve inspection/replacement	172R-S	8-18-03
SSP03-71-01	Engine oil pump inspection	T/206H	6-23-03

03 SSP total 4

02 Special Service Project

SSP02-11-01	Pilot's operating handbook revision	172R	1-21-02
SSP02-22-01	KC 140 autopilot computer inspection	172/182series	9-16-02 Recommended
SSP02-27-01	Control column universal joint inspection	172S	8-05-02
SSP02-53-01	Firewall sealant installation	172S	10-28-02
SSP02-71-01	Engine crankshaft replacement	T206H	2-01-02 AD2002-04-51 E
SSP02-71-02	Engine crankshaft replacement	T206H	8-16-02 AD2002-19-03

02 SSP total 6

01 Special Service Project

SSP01-11-01	POH revision 1	T/182T	6-18-01
SSP01-28-01	Wing-to-fuselage fuel hose and clamp insp.	T/182T	7-23-01
SSP01-73-01	Engine fuel flow divider port plug torque insp.	T182T	6-08-01

01 SSP total 3

00 Special Service Project

SSP00-25-01	Headliner insulation insp./replacement	T/206H	11-20-00
SSP00-32-01	Parker Hannifin brake cylinder insp/replace	172R-S	3-13-00
SSP00-57-01	Right wing spar cap stiffener inspection	T/206H	9-11-00
SSP00-71-02	Textron Lyc. engine rocker and rocker cover	T/206H	8-14-00

00 SSP total 4

99 Special Service Project

SSP99-11-01	Altimeter certification logbook entry	T206H	6-01-99
SSP99-11-02R1	Airplane identification data plate insp/replace	T/206H	8-16-99
SSP99-11-03	Fuel selector valve placard replacement	172R-S	8-16-99
SSP99-25-01	French seat restraint system replacement	172R-S	9-27-99
SSP99-25-02	French seat restraint system replacement	182S	9-27-99
SSP99-27-01	Rudder trim control wheel inspect./replace	206H	3-29-99
SSP99-27-02	Aileron control bellcrank stop bolts insp.	T/206H	5-18-99

99 SSP total 7

98 Special Service Project

SSP98-78-01	Engine exhaust muffler insp.	172R	2-02-98
SSP98-78-02	Engine exhaust muffler reident.	172R	2-02-98
SSP98-78-03	Engine exhaust muffler replacement	182S	2-02-98

98 SSP total 3

97 Special Service Project

SSP97-27-01	Elevator and trim pulley	172R	7-21-97
SSP97-28-01	Fuel system insp.	172R	2-24-97
SSP97-28-02	Fuel strainer and tail pipe	172R	7-21-97
SSP97-34-01	KLN 89B GPS cable	172R	9-01-97
SSP97-52-01	Cabin door latch	172R	7-21-97
SSP97-53-01	Lower. fwd. doorpost fastener	182S	9-15-97
SSP97-71-01	Eng. Crankcase breather	182S	11-20-97
SSP97-73-01	Eng. Fuel injector	172R	3-13-97

97 SSP total 8

S.N.L's pertinent to restart aircraft

SNL97-1	Cessna service information	172/182/206series	1-20-97
SNL98-4	KMA26 audio panel rack installation	172R/182S	5-04-98
SNL98-6	Starting procedures video	172R/182S	5-18-98
SNL98-13	Temporary revision numbering change	172/182/206series	12-31-98
SNL98-14	182S muffler AD alternate compliance	182S	12-23-98
SNL99-3	Propeller spinner and aft bulkhead install	172R-S	5-10-99
SNL99-6	Engine exhaust valve guide inspection	172/182/206series	6-01-99
SNL99-8	Wing tip installation procedures	172/182/206series	8-16-99
SNL99-9	Bendix/King Avionics upgrade	172/182/206series	9-13-99
SNL99-10	Heavy duty battery availability	172R-S/182S	9-13-99
SNL99-12	Engine control cable creep	172/182/206series	11-15-99
SNL99-13	Grounded braid chafe	172/182/206series	11-15-99
SNL99-14	Gyro handling	ALL	11-15-99
SNL00-1	Heavy duty flap	172R-S	1-17-00
SNL00-3	POH-log of approved supplements	172/182/206series	1-17-00
SNL00-4	Static wick replacement	172R-S	1-31-00
SNL00-8	Vacuum pump gasket installation	172/182/206series	6-05-00
SNL00-9	Crew and Passenger seat belt restraint system	172/182/206series	7-03-00
SNL00-10	Cabin air and/or water leaks	T/206H	8-14-00
SNL00-11	Approved nondestructive testing facilities	ALL	8-28-00
SNL00-13	Cessna CD-ROM compatibility with MS	ALL	11-20-00
SNL00-14	Cessna service information	ALL	12-26-00
SNL01-1	Honeywell KLN 89/89B GPS Nav. Upgrade	172/182/206series	2-05-01
SNL01-4	Test box TE04 – supplemental instructions	ALL	7-23-01
SNL02-3	Replacement instrument vacuum hose	ALL	3-18-02
SNL03-3	Alternate propeller spinner installation	172R-S	3-05-03
SNL03-4	Heavy duty flap availability	T/206H	3-17-03
SNL03-5	Winterization nose cap cover tape installation	172R-S	3-17-03
SNL03-8	Optional idle valve availability	ALL	6-23-03
SNL03-10	Maintenance practices- handling of gyro instr.	ALL	10-27-03
SNL03-11	Alternate turn coordinator availability	T/182T	11-24-03

SNL's total 31

